## Annexure C

Appendix-XIII

## PROFORMA FOR SAFE DRINKING WATER AND SANITARY CONDITION CERTIFICATE

No.

Dated: 07.06.23

It is certified that an inspection team headed by Sourish Debnath , Assistant Engineer NRHM Msd

(Name of Officers with designation) from CMOH Berhampore , Msd (Name of Department/ Office) inspected the "Sunshine International School", 64/1 Karbala Road, PO: Cossimbazar, PS: Berhampore, Dist: Murshidabad, Pin: 742102, State: West Bengal (Name & Address of the school) on 30.05.2023(date of inspection), checked the water test report submitted by the school and found that the school has potable drinking water for students and staff of the institution and is having provision for running water in the toilets and maintaining hygienic sanitation condition in the school building & the campus as per norms prescribed by the Central/State/U.T. Govt.

The above is valid for a period of 30 yrs.

Signature with Seal: Aspetant Engineer

NRHM, Msd.

Name

Designation: Assistant Engineer NRHM MS

Assistant Engineer of

the Govt. Public Health Department (PHED)/

Authorised officer of the Local Body

Name & Address of the Office / Department : .......

To

**Sunshine International School** 64/1 Karbala Road, PO: Cossimbazar, Dist: Murshidabad, Pin: 742102 ( Name & Address of the Institution)

\* The filled up certificate should be either in Hindi or English. If it is issued in vernacular language, translated notarized version in English be uploaded along with the original vernacular certificate as a single pdf.

> SUNSHINE INTERNATIONAL SCHOOL damanardo Selo